

2017 Tree Removal

366 2nd ST SE on the avenue east side of property

114 2nd AVE SW maple between sidewalk and street east side of property

264 2nd AVE SW maple between sidewalk and street east side of property

Nazarene church park maple between sidewalk and street east side of property

384 S Main AVE ash on south side

Catholic Church on 2nd AVE SE east side of property

Jim Gremmer property south of Catholic Church maple northwest side of property 4th St se and 1st Ave

548 4th ST SW maple west of driveway between sidewalk and street south side of property

Stumps to grind

482 1st AVE SW two stumps on south side of property

7th ST SW Dick Leerar property west 349 7th St Sw north side of property 2 stumps

276 7th ST SW one stump south side of property between sidewalk and street

260 7th ST SW two stumps on south side of property between sidewalk and street

City of Britt Property

Camp Park maple on south west corner of property

City park flowering crab on north west side of property

Stump on Center St property west of 817 Center st north side of property

Contractors

Remove trees and debris

Grind stumps and remove

Clean street if needed

Can dump logs and grindings at city tree dump

Responsible for locates

Repair any sidewalks or street damage or yard damage including seeding

City will fill in stump hole and seed that area